

NORTHSKY

FIVE-DEBRIS PALLET FORK
M1-1205





Part#	Description	QTY
①	Main frame	1
②	T-handle	2

- ASSEMBLY INSTALLATION
  - Always check the tractor/skid loader to make sure it is in good working condition.
  - Before clamping, ensure the “T” Handle(s) is clear of all loose debris prior to tightening.
  - Unscrew “T” Handle(s) to allow enough space to slide the attachment over the bucket.
  - Slide the clamp-on attachment all the way on. The front edge of the bucket should be completely inserted into the attachment with no extra space left in front of the bucket edge.
  - Tighten the “T” Handle(s) until the attachment is securely clamped to the bucket.
  - Re-tighten after the first use.